


USERS MANUAL
NÁVOD NA POUŽITIE

R:AMP 6



bike equipment

BATTERY INDICATOR INDIKÁTOR BATÉRIE

When the device is power-on, the power button light will indicate the battery level.
When the device is power-off, short press the power button to activate the indicator light (light will shut down automatically after 2 seconds).
Keď je zariadenie zapnuté, kontrolka vypínača bude indikovať úroveň nabitia batérie.
Keď je zariadenie vypnuté, krátkym stlačením vypínača aktivujete kontrolku stavu batérie (automaticky sa vypne po 2 sekundách).




GREEN
ZELENÁ
100%-21%




RED
ČERVENÁ
20%-11%



FLASH RED
ČER.BLIKANIE
10%-0%



WARNING UPOZORNENIE




HOW TO RECHARGE NABÍJANIE



Charging
Nabíjanie




Fully charged
Nabitá




Standard charging time
Approx. 2.5hrs (5V 2A)
Doba nabíjania: 2,5 h

WHAT'S IN V BALENÍ




HOW TO INSTALL MONTÁŽ




SWITCHING THE LIGHTING MODE ZMENA REŽIMU SVIETENIA

When you turn the light on, it lights up in the last lighting mode you used. (Mode memory function)
Po zapnutí sa svetlo rozsvieti v poslednom použítom režime svietenia. (Funkcia pamäte režimu)



OPTIONAL PARTS DOPLNKOVÉ PRÍSLUŠENSTVO



Helmet mount
Montáž na prilbu

GoPro/Garmin mount
GoPro/Garmin montáž

LUMENS/RUN TIME VÝKON / ČAS SVIETENIA

MODE	LOW	MID	HIGH	FLASH 1	FLASH 2
LUMENS	150	300	600	0-300	0-300
h:min	05:30	02:50	01:30	06:00	04:30

SPECIFICATION ŠPECIFIKÁCIA

ANSI FL 1 STANDARD

LIGHT OUTPUT 600 LUMENS	BEAM DISTANCE 106m	PEAK BEAM INTENSITY 2800cd	IMPACT RESISTANCE 1m	WATERPROOF 1m
----------------------------	-----------------------	-------------------------------	-------------------------	------------------

CE RoHS Recycle No Disposal